

#### Order #XXXXX SYM-411 Portable Counter

#### Item Qty. Description

- -- 2 16.732"h aluminum Leg (lower)
- -- 2 16.732"h aluminum Leg (lower w/ Velcro)

© 2024

- -- 2 16.732"h aluminum Leg (upper)
- -- 2 16.732"h aluminum Leg (upper w/Velcro)
- -- 1 43"w x 21.5"d Counter Base
- -- 1 43"w x 21.5"d Counter Shelf
  - 1 43"w x 21.5"d Counter Top

#### Steps:

Note: Assemble counter upside-down.

- 1) Attach upper legs to underside of Counter Top. Twist to tighten.
- 2) Connect lower Legs through Counter Shelf to upper Legs, as shown.
- 3) Place Counter Base over lower Legs & secure with wing nuts.
- 4) Turn counter unit over & affix Graphic to Velcro on front of unit.

#### Assemble unit upside-down.



Note: Velcro must face front of assembled counter.

# SETUP INSTRUCTIONS

Graphic



When assembled





**Order #XXXXX** General Information

## **General Setup Instructions**

© 2024

- Read entire setup instruction manual prior to unpacking parts and pieces.
- The setup instructions are created specifically for this configuration.
- Setup instructions are laid out sequentially in steps, including exploded views with detailed explanation for assembly.

### Cleaning & Packing

- For Cleaning Metal, Plex, & Laminate Parts: Use a MILD NON-ABRASIVE cleanser and soft cloth/paper towel to clean all surfaces.
- Keep exhibit components away from heat and prolonged sun exposure. Heat and UV exposure will warp and fade components.
- Retain all provided Packing Materials. All provided packing materials are for ease of repacking & component protection.



Part Identification - Numbering



Engaged Lock

### Disassembly

- For loss prevention, keep all knobs & connectors attached to extrusions during disassembly.







### DO NOT USE POWER TOOLS

ALL CONNECTIONS MUST **BE TIGHTLY SECURED** 



© 2024

### Top View of Each Level



